



KERATAN AKHBAR

| | | | | |
|-------------|---|------------------|------------|-----|
| AKHBAR | : | THE SUN | | |
| TARIKH | : | 28/11/2019 | MUKA SURAT | : 3 |
| JABATAN | : | SPAN | | |
| KLASIFIKASI | : | PERHATIAN | | |

Syabas conducted probe to identify cause of incidents

have been replaced.

"We carried out the investigation as part of our countermeasure without pointing fingers at any parties. It is to identify the exact cause of the incidents, particularly within the 48-hour period," Halem said.

"The pipes in front of Jalan Pinang and Jalan Dewan Bahasa are the old 300mm cement pipes which can't withhold high water pressure."

Air Selangor said a pressure logger has been installed to monitor the water pressure and to stabilise water supply.

"To mitigate the risk, we are

From
front
page

installing an endcap on the pipe at the side of the road and carrying out tapping relocation for 10 premises that are receiving water from the affected pipeline," he said.

Since Sunday, three sinkholes occurred in the golden triangle at Jalan Maharajalela, Jalan Pinang and Jalan Dewan Bahasa over three consecutive days.

The National Water Services Commission has asked Air Selangor to investigate the three sinkhole incidents and to monitor other areas at risk of such occurrence.